

SILK

ADVERTISING DIGITAL PRINTING
NEON BOX
OFFSET PRINTING T-SHIRT UNIFORM
MERCHANDISE Etc...

Telp: 7717 5300, 7725 0080

SILK UNIPESSOAL is a company in Timor Leste which provides services as listed above and Guide Post is one of Our Clients

Lecidere Office Center,
Room 101-103 Rua Avenida Direitos
Humanos, Dili - Timor Leste

SAWYER®


Ph: 7746 7848

WHY CHOOSE A SAWYER FILTER



THE 0.1 MICRON ABSOLUTE DIFFERENCE

- Sawyer's fiber walls are thicker and more robust than another Hollow Fiber Membranes. This allows for higher pressure both for filtering and for back washing. Sawyer filters can handle 60 PSI forward and 20 PSI backwards.
- Sawyer has a proprietary process of making all pores more uniform in size.
- Sawyer's proprietary process allows for more pores giving better flow and less cleaning.
- Sawyer's proprietary design has a self priming mechanism to eliminate air locks making them much easier to restart.
- Sawyer 100% tests all filters to insure no pore is larger than 0.1 micron.
- There is nothing to wear out inside the filter. If water is flowing, it's good.



THE 0.02 MICRON ABSOLUTE DIFFERENCE

- The 0.02 micron purifier has all the advantages of the 0.1 micron filter but with 0.02 micron pores.
- It is the only filter that removes viruses so effortlessly. Gravity does all the work.
- There are no harmful chemicals or heavy metals in the filter.

SAWYER FILTER REMOVAL RATES

	WATERBORN DISEASES	EPAREQU IREMENT	EXCEEDSEPA QUIREMENT	SAWYERREM OVALRATES
PURI FIER	BACTERIA WHICH CAUSE E. Cholera, Botulism, Clostridium botulinum, M. Typhoid, (Salmonella typhi), Amoeba Dysentery.	99.9999% 6log	YES	99.99999% 7log
	PROTOZOAN (CYSTS) E. Giardia, Cryptosporidium, Cyclospora	99.9% 3log	YES	99.9999% 6log
	VIRUSES E. Hepatitis A (HAV), Poliovirus, Norwalk K. Rotavirus, Adenovirus, Hepatitis E (HE V), Coxsackievirus, Echovirus, Reovirus, Astrovirus, Corona Virus (SARS)	99.99% 4log	YES	99.9997% 5.5log

TEST OF SAMPLE TAKEN BEFORE PASSING THROUGH THE SAWYER FILTER

Request for Water Quality Testing

Sample analysis reference:	- 000005801				
Requesting Organization:	- SAME / MINISTRY OF HEALTH				
2.00 Sulphate (SO ₄ ²⁻)	mg/L	√	44	250	Spectrophotometer
Bacteriological test					
16.00 Total Coliform	CFU/100mL	√	5	0	Membrane filtration
16.00 E. Coli	CFU/100mL	√	0	0	Membrane filtration
Total cost	Remark				
\$ 61.00 USD	Total Coliform is problem!				
Inspected by: _____ Head of DNSA Laboratory					

Legend: I: NS: not set; ND: not detectable; NT: not tested; NR: not result; CFU: Colony Formed Unit; TNC: too numerous to count.

TEST OF SAMPLE TAKEN AFTER PASSING THROUGH THE SAWYER FILTER

Sample analysis reference:	- 000005800				
Requesting Organization:	- SAME / MINISTRY OF HEALTH				
2.00 Sulphate (SO ₄ ²⁻)	mg/L	√	47	250	Titration Spectrophotometer
Bacteriological test					
16.00 Total Coliform	CFU/100mL	√	0	0	Membrane filtration
16.00 E. Coli	CFU/100mL	√	0	0	Membrane filtration
Total cost	Remark				
\$ 61.00 USD	NO PROBLEM.				
Inspected by: _____ Head of DNSA Laboratory					

Legend: I: NS: not set; ND: not detectable; NT: not tested; NR: not result; CFU: Colony Formed Unit; TNC: too numerous to count.

THE BENEFIT OF CONTINUOUS USE AND BACK FLUSHING CAPABILITIES

At this point we do not know what the life time limitations of the fibers are. We have working filters that have been in continuous use for over six years and we have filters which have filtered hundred thousands and of gallons of water. Sawyer's fibers are so robust, they can be back washed and re used perpetually.

- When back washing, even the stubborn dirt can be forced off the fibers.
- Sawyer's robust fibers will not "wear out" over time.
- Sawyer fibers will not break or become damaged if dropped. Only breaking the sealed casing and "playing" with fibers or freezing the cartridge after it is wet could damage the fibers.

Timor Leste authorized distributor:

MiPlug Unipessoal Lda

Director: Mr. Peter Beilby, Mobile No: +670 7733 8501

Email: beilbypeter@yahoo.com.au

Malinamoc

Hotel & Restaurant

Fully serviced and equipped large Apartments

Daily or Special Long Stay Rates

T1 - 90m2
T2 - 140 m2










Please visit us at Kampung Baru (Comoro) 1 km from Dili Airport

Call for Information or Reservations to 7723 0900 or 7775 1028


Naris Restaurant & No. 1 Supermarket

나리스식당/한국 식품

Open:
Monday-Saturday
(10:00am - 22:00pm)
Sunday CLOSED

NEW PRODUCTS



*Steaks *Grills *Korean Dishes *Lunch Box
*Conference Room *Party Room *A/C Room

Tel: 7301 6484 / 7847 6019

Address: Av. Portugal, Praia dos Coqueiros, Dili, Timor - Leste